

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

---

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 01 Arcade Creek				Left	2.10

  

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/6/2009 - 5/6/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	05/06/2009 05/06/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.78	0.78	Earthen Levee	Trim / Thin Trees	LS	M	Trim trees to at least five feet above ground level.	38.624010 ° -121.455138 °	38.624010 ° -121.455138 °		25
2	1.14	1.14	Earthen Levee	Encroachments	LS	CO	Fences	38.624800 ° -121.448808 °	38.624800 ° -121.448808 °		24
3	1.16	1.16	Earthen Levee	Encroachments	LS	CO	Fences	38.624832 ° -121.448607 °	38.624832 ° -121.448607 °		23
4	1.17	1.17	Earthen Levee	Encroachments	LS	CO	Fences	38.624850 ° -121.448428 °	38.624850 ° -121.448428 °		22
5	1.18	1.18	Earthen Levee	Encroachments	LS	CO	Fences	38.624877 ° -121.448248 °	38.624877 ° -121.448248 °		21
6	1.19	1.19	Earthen Levee	Encroachments	LS	CO	Fences	38.624900 ° -121.448037 °	38.624900 ° -121.448037 °		20
7	1.20	1.20	Earthen Levee	Encroachments	LS	C	Fences	38.624942 ° -121.447825 °	38.624942 ° -121.447825 °		19
8	1.26	1.26	Earthen Levee	Encroachments	LS	CO	Buildings	38.625300 ° -121.446767 °	38.625300 ° -121.446767 °		18
9	1.35	1.35	Earthen Levee	Encroachments	LS	CO	Fences	38.625827 ° -121.445395 °	38.625827 ° -121.445395 °		17
10	1.37	1.37	Earthen Levee	Encroachments	LS	CO	Fences	38.626000 ° -121.444978 °	38.626000 ° -121.444978 °		16
11	1.38	1.38	Earthen Levee	Encroachments	LS	CO	Fences	38.626048 ° -121.444785 °	38.626048 ° -121.444785 °		15
12	1.39	1.39	Earthen Levee	Encroachments	LS	CO	Fences	38.626085 ° -121.444580 °	38.626085 ° -121.444580 °		14
13	1.41	1.41	Earthen Levee	Encroachments	LS	CO	Fences	38.626155 ° -121.444250 °	38.626155 ° -121.444250 °		13
14	1.42	1.42	Earthen Levee	Encroachments	LS	CO	Fences	38.626212 ° -121.444082 °	38.626212 ° -121.444082 °		12
15	1.43	1.43	Earthen Levee	Encroachments	LS	CO	Landscaping	38.626325 ° -121.443928 °	38.626325 ° -121.443928 °		11
16	1.55	1.55	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627267 ° -121.442138 °	38.627267 ° -121.442138 °		10
17	1.83	1.83	Earthen Levee	Encroachments	LS	CO	Fences	38.627880 ° -121.437368 °	38.627880 ° -121.437368 °		9

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Arcade Creek	Left	2.10	05/06/2009 05/06/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
18	1.87	1.87	Earthen Levee	Encroachments	LS	CO	Landscaping	38.627827 ° -121.436633 °	38.627827 ° -121.436633 °		8
19	1.88	1.88	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627837 ° -121.436393 °	38.627837 ° -121.436393 °		7
20	1.92	1.92	Earthen Levee	Encroachments	LS	CO	Fences	38.627725 ° -121.435715 °	38.627725 ° -121.435715 °		6
21	1.93	1.93	Earthen Levee	Encroachments	LS	CO	Fences	38.627680 ° -121.435555 °	38.627680 ° -121.435555 °		5
22	1.94	1.94	Earthen Levee	Encroachments	LS	CO	Fences	38.627640 ° -121.435378 °	38.627640 ° -121.435378 °		4
23	1.95	1.95	Earthen Levee	Encroachments	LS	CO	Fences	38.627595 ° -121.435218 °	38.627595 ° -121.435218 °		3
24	1.99	1.99	Earthen Levee	Encroachments	LS	CO	Fences	38.627377 ° -121.434383 °	38.627377 ° -121.434383 °		2
25	2.00	2.00	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627318 ° -121.434208 °	38.627318 ° -121.434208 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 02 Natomas E Canal				Left	4.00
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/5/2009 - 5/6/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Natomas E Canal	Left	4.00	05/05/2009 05/06/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.39	3.92	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.635307 ° -121.470742 °	38.656998 ° -121.474858 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 03 American River				Right	3.42
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/6/2009 - 5/6/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 American River	Right	3.42	05/06/2009 05/06/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1							No issues were reported.	°	°		
								°	°		

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 04 American River				Left	11.00
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/7/2009 - 5/7/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.31	0.47	Earthen Levee	Encroachments	LS	CO	Landscaping	38.599835 ° -121.503448 °	38.600762 ° -121.500833 °		1
2	1.95	2.87	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.595053 ° -121.476993 °	38.587180 ° -121.464365 °		172
3	1.96	2.87	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.594968 ° -121.476952 °	38.587137 ° -121.464368 °		173
4	2.68	2.68	Earthen Levee	Encroachments	LS	CO	Buildings	38.588913 ° -121.467210 °	38.588913 ° -121.467210 °		2
5	2.82	2.82	Earthen Levee	Encroachments	LS	CO	Debris	38.587442 ° -121.465170 °	38.587442 ° -121.465170 °		3
6	2.84	2.84	Earthen Levee	Encroachments	WS	PO	Debris	38.587272 ° -121.464768 °	38.587272 ° -121.464768 °		4
7	2.93	2.93	Earthen Levee	Encroachments	LS	CO	Buildings	38.587250 ° -121.463138 °	38.587250 ° -121.463138 °		5
8	3.91	3.91	Earthen Levee	Encroachments	LS	PO	Fences	38.586105 ° -121.447622 °	38.586105 ° -121.447622 °		8
9	3.92	3.92	Earthen Levee	Encroachments	LS	CO	Landscaping	38.586118 ° -121.447540 °	38.586118 ° -121.447540 °		7
10	3.92	3.92	Earthen Levee	Encroachments	LS	CO	Fences	38.586327 ° -121.447382 °	38.586327 ° -121.447382 °		6
11	3.94	3.94	Earthen Levee	Encroachments	LS	CO	Fences	38.585888 ° -121.447172 °	38.585888 ° -121.447172 °		9
12	3.97	3.97	Earthen Levee	Encroachments	LS	CO	Landscaping	38.585655 ° -121.446793 °	38.585655 ° -121.446793 °		10
13	4.01	4.01	Earthen Levee	Encroachments	LS	CO	Fences	38.585367 ° -121.446262 °	38.585367 ° -121.446262 °		11
14	4.02	4.02	Earthen Levee	Encroachments	LS	CO	Fences	38.585180 ° -121.445988 °	38.585180 ° -121.445988 °		12
15	4.05	4.05	Earthen Levee	Encroachments	LS	CO	Fences	38.584923 ° -121.445655 °	38.584923 ° -121.445655 °		13
16	4.07	4.07	Earthen Levee	Encroachments	LS	PO	Fences	38.584713 ° -121.445385 °	38.584713 ° -121.445385 °		14
17	4.10	4.10	Earthen Levee	Encroachments	LS	CO	Fences	38.584485 ° -121.445042 °	38.584485 ° -121.445042 °		15

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 American River						Left	11.00	05/07/2009 05/07/2009	Clay Thomas	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
18	4.11	4.11	Earthen Levee	Encroachments	LS PO	Landscaping		38.584347 ° -121.444855 °	38.584347 ° -121.444855 °		16
19	4.12	4.12	Earthen Levee	Encroachments	LS CO	Fences		38.584237 ° -121.444680 °	38.584237 ° -121.444680 °		17
20	4.13	4.13	Earthen Levee	Encroachments	LS CO	Fences		38.584133 ° -121.444545 °	38.584133 ° -121.444545 °		18
21	4.14	4.14	Earthen Levee	Encroachments	LS CO	Fences		38.584063 ° -121.444428 °	38.584063 ° -121.444428 °		19
22	4.15	4.15	Earthen Levee	Encroachments	LS CO	Fences		38.583980 ° -121.444267 °	38.583980 ° -121.444267 °		20
23	4.16	4.16	Earthen Levee	Encroachments	LS CO	Landscaping		38.583858 ° -121.444070 °	38.583858 ° -121.444070 °		21
24	4.20	4.20	Earthen Levee	Encroachments	LS CO	Fences		38.583563 ° -121.443533 °	38.583563 ° -121.443533 °		22
25	4.22	4.22	Earthen Levee	Encroachments	LS PO	Fences		38.583367 ° -121.443205 °	38.583367 ° -121.443205 °		23
26	4.23	4.23	Earthen Levee	Encroachments	LS PO	Fences		38.583270 ° -121.443067 °	38.583270 ° -121.443067 °		24
27	4.28	4.28	Earthen Levee	Encroachments	LS PO	Fences		38.582802 ° -121.442387 °	38.582802 ° -121.442387 °		25
28	4.32	4.32	Earthen Levee	Encroachments	LS PO	Fences		38.582480 ° -121.441865 °	38.582480 ° -121.441865 °		26
29	4.35	4.35	Earthen Levee	Encroachments	LS CO	Fences		38.582218 ° -121.441345 °	38.582218 ° -121.441345 °		27
30	4.36	4.36	Earthen Levee	Encroachments	LS CO	Fences		38.582160 ° -121.441207 °	38.582160 ° -121.441207 °		28
31	4.41	4.41	Earthen Levee	Encroachments	LS CO	Landscaping		38.581868 ° -121.440340 °	38.581868 ° -121.440340 °		29
32	4.42	4.42	Earthen Levee	Encroachments	LS PO	Fences		38.581792 ° -121.440138 °	38.581792 ° -121.440138 °		30
33	4.43	4.43	Earthen Levee	Encroachments	LS PO	Fences		38.581747 ° -121.440003 °	38.581747 ° -121.440003 °		31
34	4.48	4.48	Earthen Levee	Encroachments	LS PO	Fences		38.581512 ° -121.439188 °	38.581512 ° -121.439188 °		32

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
35	4.49	4.49	Earthen Levee	Encroachments	LS	PO	Landscaping	38.581478 ° -121.439018 °	38.581478 ° -121.439018 °		33
36	4.51	4.51	Earthen Levee	Encroachments	LS	PO	Landscaping	38.581375 ° -121.438588 °	38.581375 ° -121.438588 °		34
37	4.55	4.55	Earthen Levee	Encroachments	LS	PO	Fences	38.581207 ° -121.437998 °	38.581207 ° -121.437998 °		35
38	4.56	4.56	Earthen Levee	Encroachments	LS	PO	Fences	38.581197 ° -121.437815 °	38.581197 ° -121.437815 °		36
39	4.68	4.68	Earthen Levee	Encroachments	LS	PO	Landscaping	38.580957 ° -121.435645 °	38.580957 ° -121.435645 °		37
40	4.69	4.69	Earthen Levee	Encroachments	LS	PO	Landscaping	38.580900 ° -121.435367 °	38.580900 ° -121.435367 °		38
41	4.72	4.72	Earthen Levee	Encroachments	LS	CO	Landscaping	38.580833 ° -121.434918 °	38.580833 ° -121.434918 °		39
42	4.75	4.75	Earthen Levee	Encroachments	LS	PO	Fences	38.580742 ° -121.434305 °	38.580742 ° -121.434305 °		40
43	4.77	4.77	Earthen Levee	Encroachments	LS	CO	Fences	38.580733 ° -121.433932 °	38.580733 ° -121.433932 °		41
44	4.79	4.79	Earthen Levee	Encroachments	LS	CO	Fences	38.580720 ° -121.433587 °	38.580720 ° -121.433587 °		42
45	4.84	4.84	Earthen Levee	Encroachments	LS	PO	Fences	38.580725 ° -121.432613 °	38.580725 ° -121.432613 °		43
46	4.91	4.91	Earthen Levee	Encroachments	LS	PO	Landscaping	38.580813 ° -121.431345 °	38.580813 ° -121.431345 °		44
47	4.94	4.94	Earthen Levee	Encroachments	LS	PO	Fences	38.580848 ° -121.430753 °	38.580848 ° -121.430753 °		45
48	5.10	5.10	Earthen Levee	Encroachments	LS	CO	Fences	38.581032 ° -121.427927 °	38.581032 ° -121.427927 °		46
49	5.15	5.15	Earthen Levee	Encroachments	LS	PO	Fences	38.580912 ° -121.427042 °	38.580912 ° -121.427042 °		47
50	5.19	5.19	Earthen Levee	Encroachments	LS	CO	Fences	38.580660 ° -121.426403 °	38.580660 ° -121.426403 °		48
51	5.46	5.46	Earthen Levee	Encroachments	LS	PO	Fences	38.577595 ° -121.423347 °	38.577595 ° -121.423347 °		49

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
52	5.56	5.56	Earthen Levee	Encroachments	LS	CO	Landscaping	38.576208 ° -121.423152 °	38.576208 ° -121.423152 °		50
53	5.58	5.58	Earthen Levee	Encroachments	LS	CO	Landscaping	38.576005 ° -121.423150 °	38.576005 ° -121.423150 °		51
54	5.62	5.62	Earthen Levee	Encroachments	LS	CO	Landscaping	38.575390 ° -121.423207 °	38.575390 ° -121.423207 °		52
55	5.63	5.63	Earthen Levee	Encroachments	LS	CO	Landscaping	38.575250 ° -121.423240 °	38.575250 ° -121.423240 °		53
56	5.64	5.64	Earthen Levee	Encroachments	LS	PO	Fences	38.575093 ° -121.423263 °	38.575093 ° -121.423263 °		54
57	5.66	5.66	Earthen Levee	Encroachments	LS	PO	Fences	38.574837 ° -121.423297 °	38.574837 ° -121.423297 °		55
58	5.67	5.67	Earthen Levee	Encroachments	LS	CO	Buildings	38.574648 ° -121.423348 °	38.574648 ° -121.423348 °		56
59	5.72	5.72	Earthen Levee	Encroachments	LS	CO	Fences	38.573927 ° -121.423480 °	38.573927 ° -121.423480 °		57
60	5.75	5.75	Earthen Levee	Encroachments	LS	PO	Landscaping	38.573547 ° -121.423583 °	38.573547 ° -121.423583 °		58
61	5.76	5.76	Earthen Levee	Encroachments	LS	PO	Fences	38.573403 ° -121.423642 °	38.573403 ° -121.423642 °		59
62	5.77	5.77	Earthen Levee	Encroachments	LS	PO	Landscaping	38.573240 ° -121.423697 °	38.573240 ° -121.423697 °		60
63	5.79	5.79	Earthen Levee	Encroachments	LS	CO	Landscaping	38.572918 ° -121.423760 °	38.572918 ° -121.423760 °		61
64	5.81	5.81	Earthen Levee	Encroachments	LS	PO	Landscaping	38.572748 ° -121.423818 °	38.572748 ° -121.423818 °		62
65	5.83	5.83	Earthen Levee	Encroachments	LS	CO	Buildings	38.572325 ° -121.423913 °	38.572325 ° -121.423913 °		63
66	5.85	5.85	Earthen Levee	Encroachments	LS	CO	Landscaping	38.572117 ° -121.423987 °	38.572117 ° -121.423987 °		64
67	5.87	5.87	Earthen Levee	Encroachments	LS	PO	Fences	38.571783 ° -121.424080 °	38.571783 ° -121.424080 °		65
68	5.88	5.88	Earthen Levee	Encroachments	LS	CO	Buildings	38.571688 ° -121.424112 °	38.571688 ° -121.424112 °		66

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
69	5.88	5.88	Earthen Levee	Encroachments	LS	PO	Material	38.571685 ° -121.424115 °	38.571685 ° -121.424115 °		67
70	5.89	5.89	Earthen Levee	Encroachments	LS	CO	Landscaping	38.571525 ° -121.424152 °	38.571525 ° -121.424152 °		68
71	5.91	5.91	Earthen Levee	Encroachments	LS	PO	Landscaping	38.571305 ° -121.424183 °	38.571305 ° -121.424183 °		69
72	5.92	5.92	Earthen Levee	Encroachments	LS	PO	Landscaping	38.571145 ° -121.424192 °	38.571145 ° -121.424192 °		70
73	5.97	5.97	Earthen Levee	Encroachments	LS	PO	Landscaping	38.570450 ° -121.424237 °	38.570450 ° -121.424237 °		71
74	6.00	6.00	Earthen Levee	Encroachments	LS	PO	Fences	38.569973 ° -121.424282 °	38.569973 ° -121.424282 °		72
75	6.61	6.61	Earthen Levee	Encroachments	LS	CO	Buildings	38.561643 ° -121.421262 °	38.561643 ° -121.421262 °		73
76	7.73	7.73	Earthen Levee	Encroachments	LS	CO	Fences	38.559172 ° -121.402947 °	38.559172 ° -121.402947 °		74
77	7.75	7.75	Earthen Levee	Encroachments	LS	CO	Fences	38.559227 ° -121.402647 °	38.559227 ° -121.402647 °		75
78	7.80	7.80	Earthen Levee	Encroachments	LS	CO	Fences	38.559308 ° -121.401717 °	38.559308 ° -121.401717 °		76
79	7.85	7.85	Earthen Levee	Encroachments	LS	CO	Fences	38.559367 ° -121.400938 °	38.559367 ° -121.400938 °		77
80	7.88	7.88	Earthen Levee	Encroachments	LS	CO	Fences	38.559408 ° -121.400242 °	38.559408 ° -121.400242 °		78
81	7.97	7.97	Earthen Levee	Encroachments	LS	CO	Fences	38.559833 ° -121.398785 °	38.559833 ° -121.398785 °		79
82	8.01	8.01	Earthen Levee	Encroachments	LS	CO	Fences	38.560070 ° -121.398128 °	38.560070 ° -121.398128 °		80
83	8.05	8.05	Earthen Levee	Encroachments	LS	CO	Fences	38.560340 ° -121.397388 °	38.560340 ° -121.397388 °		81
84	8.09	8.09	Earthen Levee	Encroachments	LS	CO	Fences	38.560563 ° -121.396818 °	38.560563 ° -121.396818 °		82
85	8.10	8.10	Earthen Levee	Encroachments	LS	CO	Fences	38.560647 ° -121.396660 °	38.560647 ° -121.396660 °		83

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
86	8.11	8.11	Earthen Levee	Encroachments	LS	CO	Fences	38.560725 ° -121.396470 °	38.560725 ° -121.396470 °		84
87	8.13	8.13	Earthen Levee	Encroachments	LS	CO	Fences	38.560837 ° -121.396220 °	38.560837 ° -121.396220 °		85
88	8.14	8.14	Earthen Levee	Encroachments	LS	CO	Fences	38.560907 ° -121.396043 °	38.560907 ° -121.396043 °		86
89	8.15	8.15	Earthen Levee	Encroachments	LS	CO	Fences	38.561008 ° -121.395817 °	38.561008 ° -121.395817 °		87
90	8.20	8.20	Earthen Levee	Encroachments	LS	CO	Fences	38.561325 ° -121.395067 °	38.561325 ° -121.395067 °		88
91	8.22	8.22	Earthen Levee	Encroachments	LS	CO	Fences	38.561467 ° -121.394728 °	38.561467 ° -121.394728 °		89
92	8.23	8.23	Earthen Levee	Encroachments	LS	CO	Fences	38.561540 ° -121.394513 °	38.561540 ° -121.394513 °		90
93	8.25	8.25	Earthen Levee	Encroachments	LS	CO	Fences	38.561593 ° -121.394315 °	38.561593 ° -121.394315 °		91
94	8.25	8.25	Earthen Levee	Encroachments	LS	PO	Landscaping	38.561658 ° -121.394157 °	38.561658 ° -121.394157 °		92
95	8.26	8.26	Earthen Levee	Encroachments	LS	CO	Fences	38.561658 ° -121.394152 °	38.561658 ° -121.394152 °		93
96	8.27	8.27	Earthen Levee	Encroachments	LS	CO	Fences	38.561732 ° -121.393928 °	38.561732 ° -121.393928 °		94
97	8.28	8.28	Earthen Levee	Encroachments	LS	CO	Fences	38.561802 ° -121.393697 °	38.561802 ° -121.393697 °		95
98	8.29	8.29	Earthen Levee	Encroachments	LS	CO	Fences	38.561872 ° -121.393537 °	38.561872 ° -121.393537 °		96
99	8.31	8.31	Earthen Levee	Encroachments	LS	PO	Fences	38.561972 ° -121.393323 °	38.561972 ° -121.393323 °		97
100	8.31	8.96	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.561993 ° -121.393265 °	38.565300 ° -121.382358 °		174
101	8.31	8.96	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.561993 ° -121.393265 °	38.565298 ° -121.382357 °		175
102	8.32	8.32	Earthen Levee	Encroachments	LS	CO	Fences	38.562045 ° -121.393148 °	38.562045 ° -121.393148 °		98

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 American River						Left	11.00	05/07/2009 05/07/2009	Clay Thomas	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
103	8.33	8.33	Earthen Levee	Encroachments	LS	CO	Fences	38.562120 ° -121.392983 °	38.562120 ° -121.392983 °		99
104	8.34	8.34	Earthen Levee	Encroachments	LS	CO	Fences	38.562182 ° -121.392778 °	38.562182 ° -121.392778 °		100
105	8.38	8.38	Earthen Levee	Encroachments	LS	CO	Fences	38.562430 ° -121.392083 °	38.562430 ° -121.392083 °		101
106	8.45	8.45	Earthen Levee	Encroachments	LS	CO	Landscaping	38.562840 ° -121.391040 °	38.562840 ° -121.391040 °		102
107	8.47	8.47	Earthen Levee	Encroachments	LS	CO	Fences	38.562998 ° -121.390647 °	38.562998 ° -121.390647 °		103
108	8.48	8.48	Earthen Levee	Encroachments	LS	PO	Fences	38.563108 ° -121.390452 °	38.563108 ° -121.390452 °		104
109	8.51	8.51	Earthen Levee	Encroachments	LS	PO	Landscaping	38.563238 ° -121.390073 °	38.563238 ° -121.390073 °		105
110	8.52	8.52	Earthen Levee	Encroachments	LS	PO	Fences	38.563308 ° -121.389885 °	38.563308 ° -121.389885 °		106
111	8.54	8.54	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563438 ° -121.389528 °	38.563438 ° -121.389528 °		107
112	8.55	8.55	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563508 ° -121.389347 °	38.563508 ° -121.389347 °		108
113	8.57	8.57	Earthen Levee	Encroachments	LS	PO	Fences	38.563580 ° -121.389140 °	38.563580 ° -121.389140 °		109
114	8.58	8.58	Earthen Levee	Encroachments	LS	PO	Fences	38.563678 ° -121.388938 °	38.563678 ° -121.388938 °		110
115	8.60	8.60	Earthen Levee	Encroachments	LS	CO	Fences	38.563820 ° -121.388518 °	38.563820 ° -121.388518 °		111
116	8.61	8.61	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563877 ° -121.388345 °	38.563877 ° -121.388345 °		112
117	8.61	8.61	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563877 ° -121.388343 °	38.563877 ° -121.388343 °		113
118	8.63	8.63	Earthen Levee	Encroachments	LS	CO	Landscaping	38.563945 ° -121.388137 °	38.563945 ° -121.388137 °		114
119	8.65	8.65	Earthen Levee	Encroachments	LS	CO	Fences	38.563998 ° -121.387725 °	38.563998 ° -121.387725 °		115

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 04 American River						Left	11.00	05/07/2009 05/07/2009	Clay Thomas	

  

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
120	8.66	8.66	Earthen Levee	Encroachments	LS	CO	Fences	38.564033 ° -121.387572 °	38.564033 ° -121.387572 °		117
121	8.66	8.66	Earthen Levee	Encroachments	LS	CO	Fences	38.564035 ° -121.387572 °	38.564035 ° -121.387572 °		116
122	8.68	8.68	Earthen Levee	Encroachments	LS	CO	Fences	38.564133 ° -121.387092 °	38.564133 ° -121.387092 °		118
123	8.68	8.68	Earthen Levee	Encroachments	LS	CO	Fences	38.564135 ° -121.387088 °	38.564135 ° -121.387088 °		119
124	9.54	9.54	Earthen Levee	Encroachments	LS	PO	Landscaping	38.566835 ° -121.372048 °	38.566835 ° -121.372048 °		120
125	9.61	9.61	Earthen Levee	Encroachments	LS	CO	Landscaping	38.567007 ° -121.370918 °	38.567007 ° -121.370918 °		121
126	9.64	9.64	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567115 ° -121.370330 °	38.567115 ° -121.370330 °		122
127	9.66	9.66	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567208 ° -121.370003 °	38.567208 ° -121.370003 °		123
128	9.67	9.67	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567242 ° -121.369858 °	38.567242 ° -121.369858 °		124
129	9.69	9.69	Earthen Levee	Encroachments	LS	CO	Landscaping	38.567330 ° -121.369462 °	38.567330 ° -121.369462 °		125
130	9.70	9.70	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567352 ° -121.369293 °	38.567352 ° -121.369293 °		126
131	9.72	9.72	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567423 ° -121.368910 °	38.567423 ° -121.368910 °		127
132	9.74	9.74	Earthen Levee	Encroachments	LS	CO	Fences	38.567493 ° -121.368633 °	38.567493 ° -121.368633 °		128
133	9.75	9.75	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567505 ° -121.368415 °	38.567505 ° -121.368415 °		129
134	9.78	9.78	Earthen Levee	Encroachments	LS	CO	Landscaping	38.567598 ° -121.367890 °	38.567598 ° -121.367890 °		130
135	9.79	9.79	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567628 ° -121.367612 °	38.567628 ° -121.367612 °		131
136	9.82	9.82	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567722 ° -121.367085 °	38.567722 ° -121.367085 °		132

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
137	9.84	9.84	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567887 ° -121.366793 °	38.567887 ° -121.366793 °		133
138	9.86	9.86	Earthen Levee	Encroachments	LS	PO	Landscaping	38.567873 ° -121.366410 °	38.567873 ° -121.366410 °		134
139	10.02	10.02	Earthen Levee	Encroachments	LS	PO	Landscaping	38.568542 ° -121.363643 °	38.568542 ° -121.363643 °		135
140	10.03	10.03	Earthen Levee	Encroachments	LS	CO	Landscaping	38.568620 ° -121.363453 °	38.568620 ° -121.363453 °		136
141	10.07	10.07	Earthen Levee	Encroachments	LS	PO	Landscaping	38.568822 ° -121.362768 °	38.568822 ° -121.362768 °		137
142	10.08	10.08	Earthen Levee	Encroachments	LS	CO	Fences	38.568712 ° -121.362663 °	38.568712 ° -121.362663 °		138
143	10.11	10.11	Earthen Levee	Encroachments	LS	PO	Landscaping	38.569077 ° -121.362168 °	38.569077 ° -121.362168 °		139
144	10.16	10.16	Earthen Levee	Encroachments	LS	PO	Landscaping	38.569177 ° -121.361218 °	38.569177 ° -121.361218 °		140
145	10.18	10.18	Earthen Levee	Encroachments	LS	CO	Buildings	38.569293 ° -121.361002 °	38.569293 ° -121.361002 °		176
146	10.36	10.36	Earthen Levee	Encroachments	LS	CO	Fences	38.570000 ° -121.357767 °	38.570000 ° -121.357767 °		141
147	10.40	10.40	Earthen Levee	Encroachments	LS	CO	Fences	38.570147 ° -121.357073 °	38.570147 ° -121.357073 °		142
148	10.43	10.43	Earthen Levee	Encroachments	LS	CO	Fences	38.570225 ° -121.356510 °	38.570225 ° -121.356510 °		143
149	10.47	10.47	Earthen Levee	Encroachments	LS	CO	Fences	38.570312 ° -121.355938 °	38.570312 ° -121.355938 °		144
150	10.47	10.47	Earthen Levee	Encroachments	LS	CO	Fences	38.570315 ° -121.355938 °	38.570315 ° -121.355938 °		145
151	10.50	10.50	Earthen Levee	Encroachments	LS	CO	Fences	38.570433 ° -121.355342 °	38.570433 ° -121.355342 °		146
152	10.53	10.53	Earthen Levee	Encroachments	LS	PO	Fences	38.570510 ° -121.354758 °	38.570510 ° -121.354758 °		147
153	10.56	10.56	Earthen Levee	Encroachments	LS	PO	Fences	38.570503 ° -121.354352 °	38.570503 ° -121.354352 °		148

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
154	10.59	10.59	Earthen Levee	Encroachments	LS	PO	Fences	38.570243 ° -121.353918 °	38.570243 ° -121.353918 °		149
155	10.60	10.60	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: Mayhew repair has crown blocked.	38.570230 ° -121.353798 °	38.570230 ° -121.353798 °		177
156	10.60	10.60	Earthen Levee	Encroachments	LS	PO	Fences	38.570095 ° -121.353807 °	38.570095 ° -121.353807 °		150
157	10.61	10.61	Earthen Levee	Encroachments	LS	CO	Fences	38.569990 ° -121.353758 °	38.569990 ° -121.353758 °		151
158	10.63	10.63	Earthen Levee	Encroachments	LS	PO	Fences	38.569707 ° -121.353633 °	38.569707 ° -121.353633 °		152
159	10.67	10.67	Earthen Levee	Encroachments	LS	CO	Fences	38.569158 ° -121.353370 °	38.569158 ° -121.353370 °		153
160	10.68	10.68	Earthen Levee	Encroachments	LS	PO	Fences	38.569020 ° -121.353313 °	38.569020 ° -121.353313 °		154
161	10.69	10.69	Earthen Levee	Encroachments	LS	PO	Landscaping	38.568870 ° -121.353245 °	38.568870 ° -121.353245 °		155
162	10.71	10.71	Earthen Levee	Encroachments	LS	PO	Landscaping	38.568713 ° -121.353150 °	38.568713 ° -121.353150 °		156
163	10.72	10.72	Earthen Levee	Encroachments	LS	PO	Landscaping	38.568512 ° -121.353078 °	38.568512 ° -121.353078 °		157
164	10.73	10.73	Earthen Levee	Encroachments	LS	PO	Fences	38.568355 ° -121.353033 °	38.568355 ° -121.353033 °		158
165	10.74	10.74	Earthen Levee	Encroachments	LS	PO	Fences	38.568227 ° -121.352997 °	38.568227 ° -121.352997 °		159
166	10.75	10.75	Earthen Levee	Encroachments	LS	PO	Fences	38.568112 ° -121.352942 °	38.568112 ° -121.352942 °		160
167	10.76	10.76	Earthen Levee	Encroachments	LS	CO	Fences	38.567993 ° -121.352852 °	38.567993 ° -121.352852 °		161
168	10.81	10.81	Earthen Levee	Encroachments	LS	PO	Fences	38.567328 ° -121.352478 °	38.567328 ° -121.352478 °		162
169	10.82	10.82	Earthen Levee	Encroachments	LS	CO	Fences	38.567145 ° -121.352380 °	38.567145 ° -121.352380 °		163
170	10.86	10.86	Earthen Levee	Encroachments	LS	CO	Landscaping	38.566788 ° -121.351777 °	38.566788 ° -121.351777 °		164

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 American River	Left	11.00	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
171	10.90	10.90	Earthen Levee	Encroachments	LS	PO	Fences	38.554763 ° -121.346112 °	38.554763 ° -121.346112 °		170
172	10.97	10.97	Earthen Levee	Encroachments	LS	PO	Fences	38.564960 ° -121.348975 °	38.564960 ° -121.348975 °		166
173	10.97	10.97	Earthen Levee	Encroachments	LS	PO	Fences	38.563338 ° -121.350295 °	38.563338 ° -121.350295 °		171
174	10.97	10.97	Earthen Levee	Encroachments	LS	CO	Landscaping	38.561302 ° -121.348837 °	38.561302 ° -121.348837 °		169
175	10.97	10.97	Earthen Levee	Encroachments	LS	PO	Landscaping	38.564645 ° -121.349090 °	38.564645 ° -121.349090 °		167
176	10.97	10.97	Earthen Levee	Encroachments	LS	PO	Fences	38.565930 ° -121.350028 °	38.565930 ° -121.350028 °		165
177	10.97	10.97	Earthen Levee	Encroachments	LS	CO	Fences	38.564995 ° -121.348150 °	38.564995 ° -121.348150 °		168

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 05 Sacramento River				Left	0.40
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/7/2009 - 5/7/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Sacramento River	Left	0.40	05/07/2009 05/07/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.11	0.11	Earthen Levee	Encroachments	LS	PO	Landscaping	38.594850 ° -121.506452 °	38.594850 ° -121.506452 °		2
2	0.15	0.15	Earthen Levee	Encroachments	LS	PO	Landscaping	38.594310 ° -121.506360 °	38.594310 ° -121.506360 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 06 Linda Creek				Left	1.30
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/5/2009 - 5/5/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 Linda Creek	Left	1.30	05/05/2009 05/05/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	1.30	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.657390 ° -121.474542 °	38.662235 ° -121.452433 °		3
2	0.02	1.30	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.657390 ° -121.474425 °	38.662233 ° -121.452433 °		2
3	0.15	0.93	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	38.657242 ° -121.471915 °	38.661953 ° -121.459010 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 07 Arcade Creek				Right	1.90
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/5/2009 - 5/5/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Arcade Creek	Right	1.90	05/05/2009 05/05/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.04	0.78	Earthen Levee	Vegetation	WS	C	Control annual grass and weeds on the levee slopes and easements.	38.620638 ° -121.466987 °	38.624787 ° -121.455618 °		1
2	0.04	0.74	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.620680 ° -121.467005 °	38.624820 ° -121.456342 °		17
3	1.54	1.54	Earthen Levee	Encroachments	LS	PO	Landscaping	38.627680 ° -121.442342 °	38.627680 ° -121.442342 °		2
4	1.56	1.56	Earthen Levee	Encroachments	LS	CO	Fences	38.627682 ° -121.442113 °	38.627682 ° -121.442113 °		3
5	1.56	1.56	Earthen Levee	Encroachments	LS	CO	Fences	38.627707 ° -121.441965 °	38.627707 ° -121.441965 °		4
6	1.65	1.65	Earthen Levee	Encroachments	LS	CO	Fences	38.627620 ° -121.440467 °	38.627620 ° -121.440467 °		5
7	1.68	1.68	Earthen Levee	Encroachments	LS	CO	Fences	38.627868 ° -121.439962 °	38.627868 ° -121.439962 °		6
8	1.69	1.69	Earthen Levee	Encroachments	LS	CO	Buildings	38.627935 ° -121.439758 °	38.627935 ° -121.439758 °		7
9	1.72	1.72	Earthen Levee	Encroachments	LS	CO	Buildings	38.628102 ° -121.439283 °	38.628102 ° -121.439283 °		8
10	1.74	1.74	Earthen Levee	Encroachments	LS	CO	Fences	38.628197 ° -121.438863 °	38.628197 ° -121.438863 °		9
11	1.77	1.77	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628273 ° -121.438255 °	38.628273 ° -121.438255 °		10
12	1.79	1.79	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628297 ° -121.437995 °	38.628297 ° -121.437995 °		11
13	1.80	1.80	Earthen Levee	Encroachments	LS	PO	Fences	38.628307 ° -121.437842 °	38.628307 ° -121.437842 °		12
14	1.81	1.81	Earthen Levee	Encroachments	LS	PO	Fences	38.628303 ° -121.437693 °	38.628303 ° -121.437693 °		13
15	1.81	1.81	Earthen Levee	Encroachments	LS	PO	Fences	38.628303 ° -121.437530 °	38.628303 ° -121.437530 °		14
16	1.83	1.83	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628295 ° -121.437282 °	38.628295 ° -121.437282 °		15
17	1.84	1.84	Earthen Levee	Encroachments	LS	CO	Landscaping	38.628262 ° -121.436985 °	38.628262 ° -121.436985 °		16

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 08 Magpie Creek Diversion				Left	1.50
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/5/2009 - 5/5/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Magpie Creek Diversion	Left	1.50	05/05/2009 05/05/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.07	1.48	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This levee is a patrol road. Limited access.	38.665677 ° -121.431967 °	38.660740 ° -121.429255 °		2
2	1.07	1.48	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: This levee is a patrol road. Limited access.	38.665668 ° -121.431955 °	38.660728 ° -121.429247 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway			Bank	Unit Miles
Unit No. 09 American River			Right	4.50

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	5/6/2009 - 5/6/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 American River	Right	4.50	05/06/2009 05/06/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	1.13	1.13	Earthen Levee	Encroachments	LS	PO	Landscaping	38.563040 ° -121.402168 °	38.563040 ° -121.402168 °		3
2	3.11	3.24	Earthen Levee	Encroachments	LS	CO	Fences	38.576423 ° -121.419117 °	38.578248 ° -121.418475 °		2
3	3.24	3.32	Earthen Levee	Encroachments	LS	PO	Fences	38.578258 ° -121.418475 °	38.579363 ° -121.418100 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 10 American River				Right	4.00
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/6/2009 - 5/6/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 10 American River	Right	4.00	05/06/2009 05/06/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1							No issues were reported.	°	°		
								°	°		

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable      PO : Partially Obstructing      C : Corrected  
M : Minimally Acceptable      CO : Completely Obstructing  
U : Unacceptable      N : Not Inspected



**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2009 Levee Inspection Results**

**American River Flood Control District**

Waterway				Bank	Unit Miles
Unit No. 11 New Linda Creek				Left	0.74
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)	
Unit Maintenance Rating (Fall Only)					
Date of Inspection	5/5/2009 - 5/5/2009				
DWR Inspector	Clay Thomas				
Accompanied By					

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to : DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.


**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2009**

**American River Flood Control District**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 11 New Linda Creek	Left	0.74	05/05/2009 05/05/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.74	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.662420 ° -121.457872 °	38.666487 ° -121.451203 °		3
2	0.00	0.74	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.662423 ° -121.457872 °	38.667815 ° -121.447490 °		2
3	0.00	0.74	Earthen Levee	Vegetation	WS		Control annual grass and weeds on the levee slopes and easements. Inspector Comments: L/M 0.00 starts at bike trail,going D/S. L/M 0.00 going U/S is unit 8 magpie crk. The V 1 does not apply, this is for GPS.	38.667982 ° -121.447555 °	38.662538 ° -121.457848 °		1

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected  
C : Corrected